



# Guide for selection of Contact Wheel



## PLAIN FACE CONTACT WHEEL

- Best Suited for very fine Polishing
- Maximum Contact Area
- Lowest unit grain pressure



- 20° Shore extra soft
- 30° Shore very soft
- 40° Shore soft
- 60° Shore medium
- 80° Shore hard
- 90° Shore very hard



## Softer the wheel, finer the finish




## EFFECT OF CONTACT WHEEL AREA ON PRESSURE



Serration also help in controlling break down of grains and flexing action on Abrasive

## EFFECT OF CONTACT WHEEL SERRATION ON MINERAL WEAR



## Most common Contact Wheel profile

